




2019 ASHOK LEYLAND VIKING ALPSV 4-251  
BS IV  
KRISHNA

Autoinspekt Rating **5**



Tyre Life  
25% Life

Transmission  
Manual

Odometer  
0 KM

V-DE-DUPE +ve

VALUATION PRICE ₹  
**12,98,000**



Registration Number **AP39V3999**  
Vehicle Type **Transport**



No Damage Reported



Manufacturing Month / Year **Feb 2019**  
Registration Month / Year **Jun 2019**

**Repo**



Vehicle Ownership **1 Owner, Yamani Rama Koteswara Rao**  
RC Status **NA**

Report Request By  
**HINDUJA LEYLAND FINANCE LTD**



Insurance & Tax **NA, NA**  
HPA Status , HPA Bank **No, na**

Major issues



NO DAMAGE VEHICLE



Chassis Number **MB1PREHDXKEHD0973**  
Engine Number **KHEZ403656**

Inspection Location

GM8QFQ5, Prasadampadu, currency nagar,  
Vijayawada, Andhra Pradesh 521108, India

Rating	Vehicle Condition	Engine Condition
10 or 9	Excellent	Excellent
8 or 7	Good	Good
6 or 5	Average	Average
4 or 3	Bad	Bad
2 or 1	Scrap	No Engine

Vehicle Summary :  
chassis number rusted



Approved by  
*G. Praveen Kumar*  
G.Praveen Kumar,  
Head e-Business.  
www.autoinspekt.com  
Use your smart  
phone to scan the  
QR code and get  
detailed  
Autoinspekt report

Vehicle Rating And Pricing

Vehicle Details


 VAHAN DETAILS

Owner Name	Yamani Rama Koteswara Rao		
Present Address	--		
Permanent Address	flat no 1 lotus residency ,navabharath nagar 1st line 3rd cross road ,guntur		
Financier	--		
Insurer	NATIONAL INSURANCE COMPANY LTD		
REGISTRATION NUMBER	AP39V3999	REGISTRATION DATE	19-Jun-2019
Registered at RTO	RTA GUNTUR	RC Status	--
Challan	--	Manufacturing Date	02/2019
OWNER SERIAL NUMBER	1	Vehicle Model	ALPSV 4/251
Vehicle Make	Ashok Leyland Ltd	Fuel	DIESEL
Color	RED	Fuel Norms	BHARAT STAGE IV
Chassis Number	MB1PREHDXKEHD0973	Engine Cubic Capacity	5759.0
Engine Number	KHEZ403656	NCRB Status	--
Vehicle Category	COCT	Blacklist Status	--
Vehicle Class Description	Contract Carriage	NOC Details	--
Body Type	Saloon	Permit No	AP007/8439/TVP/2019
Mobile No	--	Permit Issue Date	--
RC Fitness Validity	16-Jan-2024	Permit Valid from Date	21-Jun-2019
RC Tax Validity	30-Jun-2023	Permit Valid upto Date	--
Insurance Policy Number	753	Permit Type	All India()
Insurance Validity	30-Sep-2022	RC Status as on	24-Feb-2024



### LOAD BODY



LOAD BODY TYPE	BUS	
LOAD BODY BUILD	NORMAL BODY	
TAIL GATE	AVERAGE	6/10
LEFT SIDE GATE (FIXED)	AVERAGE	6/10
RIGHT SIDE GATE (FIXED)	AVERAGE	6/10
LOAD FLOOR	AVERAGE	6/10
OVERALL LOAD BODY	AVERAGE	6/10
CHASSIS CONDITION	AVERAGE	6/10
NO OF TYRES	6 TYRES	
FUEL	DIESEL	
TANKER BODY TYPE	NA	



### CABIN



BUMPER	AVERAGE	6/10
HEAD LAMPS	AVERAGE	6/10
DOOR - LEFT	AVERAGE	6/10
DOOR - RIGHT	AVERAGE	6/10
DASHBOARD	AVERAGE	6/10
NUMBER OF SEATS	31 SEATS	
DRIVER SEAT	GOOD	
AC	NO	
CO - DRIVER SEAT	GOOD	
ABS	NO	



## SYSTEMS & FUNCTIONS



ENGINE	
CONDITION	AVERAGE
AXLE CONFIGURATION	4X2
ENGINE OIL LEAKS	NO
DIESEL PUMP	AVERAGE 6/10
IGNITION SYSTEM	AVERAGE 6/10
TRANSMISSION	AVERAGE 6/10
GEARSHIFT	AVERAGE 6/10
CLUTCH ENGAGEMENT	AVERAGE 6/10
STEERING (POWER)	AVERAGE 6/10
BRAKE (AIR)	AVERAGE 6/10
DIFFERENTIAL	AVERAGE 6/10
SUSPENSION	AVERAGE 6/10
CUBIC CAPACITY (CC)	5759.0 CC

BATTERY	KEY NOT AVAILABLE
STARTER MOTOR	GOOD
ALTERNATOR	GOOD



## VEHICLE CONDITION & DOCUMENT DETAILS



VEHICLE CONDITION	TOWED (KEY NA, BATTERY NA, TYRE MISSING, BREAKDOWN)		
PARKING LOCATION	YARD	INSURANCE TYPE	NA
RC STATUS	NA	FC VALIDITY	16/01/2024
ROAD PERMIT	23/02/2024	REPO DATE	04/10/2023
YARD	VENKAT STOCK YARD - KRISHNA		



Approved by

G.Praveen Kumar,  
Head e-Business.  
www.autoinspekt.com



Tyre Life 25%



Tyre Life 25%



Tyre Life 25%



Tyre Life 25%



Tyre Life 25%



Tyre Life 25%



Tyre Life NA



Tyre Life NA



Tyre Life NA



Tyre Life NA

**DISCLAIMER**

- This report is generated by Autoinspekt - A division of Mahindra First Choice Wheels Ltd (MFCW) at the sole request of the party whom this report is addressed and is to be used solely by the said party for the stated purpose only. Autoinspekt will not be held liable for any loss or liability sustained by any third party relying on the Valuation Report. Autoinspekt has relied on the odometer reading at the time of inspection / valuation and is not responsible for verifying the genuineness thereof. Physically not verified.
- As there is no standard price list for pre-owned / used vehicles, the vehicle valuation indicated in the report is our opinion on the market value of the vehicle at the time of our inspection / valuation, based on our standard valuation methodology and procedures. Actual realization may differ from the valuation indicated in the report and Autoinspekt (including its directors and employees) will not be held liable for any direct, indirect, consequential or exemplary damages for any loss resulting from use of this report. Autoinspekt is not responsible for verifying the genuineness of the title documents of the vehicle and its professional opinion on valuation of the car is primarily based on the condition of the vehicle at the time of inspection / valuation.



Approved by

G.Praveen Kumar,  
Head e-Business.  
www.autoinspekt.com